

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404212207

Date Received:

05/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

HARKINS, LIZ

lharkins@austinexploration.com

HART, TIMOTHY B

thart@fremontpetroleum.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 690200751

Inspection Date: 10/16/2020

FIR Submit Date: 10/21/2020

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 459837

Location Name: JW Powell Number: 23-35 County: FREMONT

Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.348638 Longitude: -105.190784

FACILITY - API Number: 05-043-00 Facility ID: 459836

Facility Name: JW Powell Number: 23-35

Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.348638 Longitude: -105.190784

CORRECTIVE ACTIONS:

1 CA# 142853

Corrective Action: Comply with 1002.c

Date: _____

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: Soil piles have been replaced and seeded. ECMC inspection doc No. 690202699, conducted on 3/15/2022, confirmed compliance with this CA.

ECMC Decision: _____

ECMC
Representative:

2 CA# 142854

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The topsoil has been replaced at the south side of the location and the location has been reduced in size. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision:

ECMC
Representative:

3 CA# 142855

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/11/2020

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The erosion was repaired and BMP's have been installed. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith

Signed:

Title: Staff Engineer

Date: 5/21/2025 11:57:13 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404212207	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files