

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404212326

Date Received:
05/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>HART TIMOTHY</u>		<u>thart@fremontpetroleum.com</u>
<u>HARKINS LIZ</u>		<u>lharkins@austinexploration.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 690201142
Inspection Date: 02/09/2021 FIR Submit Date: 02/11/2021 FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC Company Number: 10412
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 459837

Location Name: JW Powell Number: 23-35 County: FREMONT
Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6
Latitude: 38.348638 Longitude: -105.190784

FACILITY - API Number: 05-043-00 Facility ID: 459836

Facility Name: JW Powell Number: 23-35
Qtrqtr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6
Latitude: 38.348638 Longitude: -105.190784

CORRECTIVE ACTIONS:

1 CA# 146453

Corrective Action: Comply with 1002.c Date: 10/16/2020

Response: CA COMPLETED Date of Completion: 03/15/2022

Operator Comment: Soil piles have been replaced and seeded. ECMC inspection doc No. 690202699, conducted on 3/15/2022, confirmed compliance with this CA.

ECMC Decision: _____

ECMC Representative:

2 CA# 146454

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 10/16/2020

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The topsoil has been replaced at the south side of the location and the location has been reduced in size. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision:

ECMC Representative:

3 CA# 146455

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 07/20/2019

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The topsoil has been replaced at the south side of the location and the location has been reduced in size. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision:

ECMC Representative:

4 CA# 146456

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/11/2020

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The erosion was repaired and BMP's have been installed. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith

Signed:

Title: Staff Engineer

Date: 5/21/2025 12:06:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404212326	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files