

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404212432

Date Received:

05/21/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

HART TIMOTHY

[dnr\\_cogccenforcement@state.co.us](mailto:dnr_cogccenforcement@state.co.us)

[thart@fremontpetroleum.com](mailto:thart@fremontpetroleum.com)

ECMC INSPECTION SUMMARY:

FIR Document Number: 690202173

Inspection Date: 10/15/2021

FIR Submit Date: 10/18/2021

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 459837

Location Name: JW Powell Number: 23-35 County: FREMONT

Qtrqr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.348638 Longitude: -105.190784

FACILITY - API Number: 05-043-00 Facility ID: 459836

Facility Name: JW Powell Number: 23-35

Qtrqr: NESW Sec: 35 Twp: 19S Range: 70W Meridian: 6

Latitude: 38.348638 Longitude: -105.190784

CORRECTIVE ACTIONS:

1 CA# 156923

Corrective Action: Comply with 1002.c

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: Soil piles have been replaced and seeded. ECMC inspection doc No. 690202699, conducted on 3/15/2022, confirmed compliance with this CA.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 156924

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The topsoil has been replaced at the south side of the location and the location has been reduced in size. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

3 CA# 156925

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The topsoil has been replaced at the south side of the location and the location has been reduced in size. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

4 CA# 156926

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator Comment: The erosion was repaired and BMP's have been installed. ECMC inspection Doc No. 690202699, conducted on March 15, 2022, confirmed completion of this CA.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith

Signed: \_\_\_\_\_

Title: Staff Engineer

Date: 5/21/2025 12:22:13 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files