

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404212608

Date Received:

05/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

HARKINS, LIZ

lharkins@austinexploration.com

HART, TIMOTHY B

thart@fremontpetroleum.com

dnr_cogccenforcement@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 690202229

Inspection Date: 10/27/2021

FIR Submit Date: 10/29/2021

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 429883

Location Name: Pathfinder Number: C 14-01 1 County: FREMONT

Qtrqtr: SWS Sec: 1 Twp: 20S Range: 70W Meridian: 6

Latitude: 38.333410 Longitude: -105.179460

FACILITY - API Number: 05-043-00 Facility ID: 429882

Facility Name: Amerigo Vespucci Number: 1

Qtrqtr: SWS Sec: 1 Twp: 20S Range: 70W Meridian: 6

Latitude: 38.333410 Longitude: -105.179460

CORRECTIVE ACTIONS:

2 CA# 157324

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 02/14/2020

Response: CA COMPLETED

Date of Completion: 03/15/2022

Unused equipment was removed from the location. ECMC inspection, doc no. 690202695, conducted 3/15/2022, confirmed CA completed.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

3 CA# 157325

Corrective Action: Comply with the 1003 interim reclamation rules.

Date: 02/28/2020

Response: CA COMPLETED

Date of Completion: 12/01/2022

Operator
Comment:

Interim reclamation has been performed; the topsoil piles have been replaced and unused areas of the location have been reclaimed. Seeding and straw mulch was applied to disturbed soils. ECMC Inspection, doc no. 690203641, conducted 12/1/2022, confirmed Corrective Actions completed.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith

Signed:

Title: Staff Engineer

Date: 5/21/2025 12:56:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404212608	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files