



00243052

**RADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT****NOV 24 1995**

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 075 - 5831		LEASE NAME: State Propst 2	
LOCATION: NENE 15-10N-53		OPERATOR: Western Op	
DATE: 11-20-95		INSPECTOR: Ed Brinkley	
Insp. Type: SR	Insp. Status: PA	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	hole plugged, restoration incomplete	
Pits (Reserve/Production) (Rule 902, 903, 904)	partially closed-	
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	2-500, VHT, rods, tank, Flowlines	
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)	(C)	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Remove equipment and restore site. All Flowlines belonging to third party contractors must be removed from the field.

Date Corrective Action Required By: 12-20-95 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.