

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/30/2025

Submitted Date:

05/29/2025

Document Number:

699700472**FIELD INSPECTION FORM**Loc ID 414396 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kasten, Matt		mkasten@laramie-energy.com	<a href="#">Laramie Energy</a>
, laramie		cogccnotifications@laramie-energy.com	<a href="#">all inspections</a>
Cholas, Nick		nick.cholas@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
159504	CENTRALIZED EP WASTE MGMT FAC	AC	01/23/2015		-	POND 10	EI
463660	SPILL OR RELEASE	CL	04/01/2021		-	Pond 10	EI
489978	SPILL OR RELEASE	AC	05/01/2025		-	Pond 10 Discharge Line	EI

**General Comment:**[ECMC Environmental Inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)



**Environmental****Spills/Releases:**Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: See Initial Form 19 Doc #404184616 and Supplemental Form 19 Doc #404193951, 404210524 & 404217242 for more information. ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the point of release as well as the irrigation ditch, irrigation pond and Conn Creek. Potentially impacted material was observed in the areas outlined in Site Diagram Pond 10 Discharge Line Doc #404195519. A hydrovac crew was present on location remediating the impacts adjacent to the irrigation ditch. The irrigation ditch head gate that feeds from Conn Creek was closed at time of inspection. The irrigation pond water had been removed via pump and approximately 2-3 feet of water remained in the irrigation pond. During inspection of the irrigation pond ECMC staff observed what appeared to be a sheen on the surface of the pond. The sheen appeared to originate from the inlet of the pond in the area where the residual water from the irrigation ditch was flowing into the pond. The Operator was contacted via cell phone and immediately made their way to the location. Other Doc #404195880 states "Noted that hydrovac had multiple stains and had issues that day with breakdowns. Assumption made that during spill path removal, Hydrovac companies breakdown/stains were being washed during clean up and made its way into irrigation ditch resulting in sheen.". Operator personnel collected samples of the pond water where the sheen was originating from and installed booms to prevent the spread of the sheen across the pond. Multiple waterfowl were present within the pond area when the sheen was initially observed by staff. ECMC staff did not observe any sheen or visible impacts on Conn Creek at time of inspection. See attached Photo Log for details.

Corrective Action: Comply with COAs on Form 19 Initial and Supplementals.

Date: \_\_\_\_\_

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700473	20250430 Photo Log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073568">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7073568</a>