

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4630 From entrance to location



Photo # 4631 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022




Photo # 4632 Location



Photo # 4633 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4634 Location



Photo # 4635 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4636 Location



Photo # 4637 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



**Photo # 4638 Unused flowline lacks lockout tagout (OOSLAT)
/not in compliance with CECMC rules**



**Photo # 4639 Unused flowline lacks lockout tagout (OOSLAT)
/not in compliance with CECMC rules**

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4640 Unused flowline near separator locked but lacks required tag/not in compliance with CECMC rules



Photo # 4641 Unused flowline near separator locked but lacks required tag/not in compliance with CECMC rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4642 Emergency contact # on sign at entrance to location incorrect/# is disconnected & not in service



Photo # 4643 Emergency contact # on sign at entrance to location incorrect/# is disconnected & not in service

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4644 Emergency contact # on wellhead sign incorrect/# is disconnected & not in service



Photo # 4645 Staining in secondary containment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4646 Staining in secondary containment



Photo # 4647 Staining in secondary containment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 4648 Production tank not in compliance with rule 425



Photo # 4649 Production tank not in compliance with rule 425