



Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#1
Emerald 93 wellhead.
Source of spill

Jun 4, 2025 12:24:34 PM
40.11023636441678N 108.91812125220895W
70709 Colorado 139
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#2
Emerald 93 wellhead.
Source of spill. Some
fluid in cellar.

Jun 4, 2025 12:25:02 PM
40.11028053704649N 108.91805226914585W
Unnamed Road
Rangely
Rio Blanco County



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jun 4, 2025 12:25:08 PM
40.11027789674699N 108.9180531911552W
Unnamed Road
Rangely
Rio Blanco County
Colorado

Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#3



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#4 apparent low
spot of pad.



Jun 4, 2025 12:25:54 PM
40.1102723646909N 108.91764205880463W
Unnamed Road
Rangely
Pio Blanco County



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#5 pad

Jun 4, 2025 12:25:17 PM
40.11027718428522N 108.91804003156722W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#6

Jun 4, 2025 12:25:14 PM
40.11027592699975N 108.91804547980428W
Unnamed Road
Rangely
Rio Blanco County
Colorado



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#7 location berm
around pad. It was
reported that the spill
stayed on pad. Inspection
appeared to confirm this
report.





Jun 4, 2025 12:26:32 PM
40.11046770494431N 108.9177320804447W
Unnamed Road
Dangshu

Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#8 looking across
pad toward wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jun 4, 2025 12:26:50 PM
40.11048597749323N 108.91779871657491W
Unnamed Road
Rangely

Inspection Photos

Location Name: Emerald 93x
spill

Spill Id:489970

Inspection Date: 6/04/2025

Photo#9 Low spot on
pad, this is the area that
shall be sampled.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources



Jun 4, 2025 12:27:25 PM
40.1104969996959N 108.91804506070912W
Unnamed Road
Rangely
Rio Blanco County

Inspection Photos
Location Name: Emerald 93x
spill
Spill Id:489970
Inspection Date: 6/04/2025

Photo#10 area on pad
that had hydrocarbon
staining. Note lat/long on
photo. Visual staining
shall be removed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources