

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8243 Entrance to location



Photo # 8244 Location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8247 Emergency Contact Number is not in service, additionally quarter/quarter section is illegible /not in compliance with CECMC rules



Photo # 8287 Emergency Contact Number on all signs on location are not in service/not in compliance with CECMC rules

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8258 Location



Photo # 8273 Location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8286 Location



Photo # 8296 NW corner of location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8297 SW corner of location



Photo # 8298 SE corner of location

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8300 NE corner of location



Photo # 8268 Staining around heater on separator

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8271 PRV vent line & Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 8301 Debris

Inspection/Audit Photos

Location: GUNNISON ENERGY LLC FEDERAL 10-90-32 PAD

Location ID: 324459

Date: 06/11/2025



Photo # 8303 Debris

