

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/13/2025

Document Number:

708906726

FIELD INSPECTION FORM

Loc ID 311622	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 20 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10844 Name of Operator: QB ENERGY OPERATING LLC Address: 1001 17TH STREET SUITE 1600 City: DENVER State: CO Zip: 80202				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278668	WELL	PR	03/01/2012	GW	045-10911	SAVAGE FEDERAL 10-7D (RJ10)	PR
278669	WELL	PR	06/07/2012	GW	045-10912	SAVAGE FEDERAL 10-9 (RJ10)	PR

General Comment:**CECMC Inspection/Audit Report Summary**

On 06/12/2025 at approximately 14:06 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at QB ENERGY OPERATING LLC SAVAGE FEDERAL 10-7D (RJ10) Pad

Location # 311622 in Garfield County Colorado.

Location is within Black Bear Habitat area & in close proximity to High Priority/Density Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Tanks & Berms - Multiple holes in secondary containment liner/liner needs maintenance with a CA date of 07/03/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Any corrective actions from previous inspections/audits that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Sign at entrance to location			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	Signs at separators			
Corrective Action:				Date:
Type	OTHER			
Comment:	Upon the Director's approval of a Form 9 the Buying Operator will have 60 days to replace or update all signs at the Oil and Gas Location so that the signs comply with Rule 605.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911/970-285-2615			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	DEBRIS			
Comment:	Debris - please refer to photo log			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 2		corrective date
Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Summit Midstream		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	500 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient		Inadequate
Comment:	Multiple holes in secondary containment liner/liner needs maintenance, additionally the liner is deteriorating in multiple areas/liner needs maintenance			
Corrective Action:	The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.			
			Date:	07/03/2025

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 278668	Type: WELL	API Number: 045-10911	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 278669	Type: WELL	API Number: 045-10912	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in most sections
Berms						
		Ditches				
		Sediment Traps				
Compaction						Small amount of light compaction
		Culverts				
Gravel						Sparse to none in areas
		Compaction				Small amount of light compaction

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Tanks & Berms for corrective action & also refer to Signs/Marker & Housekeeping for comments.	smelserw	06/12/2025
Dual lease - Shared facilities with the FEDERAL J-10-7-94-S location # 311570		
Any corrective actions from previous inspections/audits that have not been addressed are still applicable.		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708906727	Inspection/Audit 708906726 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7094732
708906728	Inspection/Audit 708906726 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7094733