

# Inspection Photos

05/30/2025

**Operator:** QB ENERGY OPERATING LLC

#10844

**Location ID:** 334872

**Inspection Doc:** 719200007

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334872



**Photo 1:** Photos provide an overview of the Location looking southeast and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334872



**Photo 2:** Photo taken from the northern end of the Location provide an overview of the Location looking southwest. An active spill remediation is occurring at the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334872



**Photo 3:** Photo example of undesirable plant species observed on the northern and central portions of the Location. Field bindweed has established at the edges of the interim areas and on the pad.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334872



**Photo 4:** Photo example of an undesirable plant species, clasping pepperweed, observed throughout the Location.



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334872



**Photo 5:** An unused produced water tank was observed at the Location. Removal is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334872



**Photo 6:** A photo example showing signs of light sediment tracking observed on the eastern portion of the Location. Gravel has not been applied to the entire pad. BMP's show signs of disrepair; maintenance is advised.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources