

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/05/2025

Submitted Date:

06/16/2025

Document Number:

717900235**FIELD INSPECTION FORM**Loc ID 318666 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kauffman, KPK		cogcc@kpk.com	All Inspections
Kari Brown		kari.brown@state.co.us	
,		rwatzman@kpk.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 485896 Julian Pluss #1 TB. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Site is inundated with weeds.

Corrective Action: Comply wiith rule 606.

Date: 06/30/2025

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: No spills observed during the inspection.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Berms at the tanks and separator are inadequate for containing a potential spill or release.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: 06/30/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:

No spills or releases observed during inspection.

Corrective Action:

Date:

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900236	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7098595

Date Run: 6/17/2025 Doc [#717900235]

Page 3 of 3