

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2025

Submitted Date:

06/17/2025

Document Number:

707801660

FIELD INSPECTION FORMLoc ID 324671 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All inspections
Beasley, Nolan		nolan.beasley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212371	WELL	IJ	07/01/2023	ERIW	057-06264	MCCALLUM UNIT 109	IJ

General Comment:ECMC Inspection Report Summary

On Friday 6/13/2025, I, Inspector Scott Ramsey conducted a routine inspection/audit at KPK McCallum 109, at location # 324671 in Jackson county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal UIC operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife black bear Management and Density habitat.

Last MIT was done 5/11/2022.

During this inspection the following possible compliance issues were observed:

1. No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.

2. Well signage is lacking information.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	<p>1. Well signage is lacking information. Within 60 days after a new Well is Completed, including each Well on a Multi-Well Site, or an existing sign is replaced or modified, a permanent sign will be conspicuously located at the wellhead and will identify:</p> <p>A. The Well name; B. The API number; and C. Its legal location, including the quarter/quarter section. When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign:</p> <p>A. Name of the Operator; B. Telephone number at which the Operator can be reached at all times; C. Telephone number for local emergency services (911 where available); and D. The public road used to access the Well.</p>		
Corrective Action:	Provide proper signage	Date:	07/25/2025

Emergency Contact Number:

Comment:	911/303-825-4822	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Other	# 1		corrective date
Comment:	Injection well		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	212371	Type:	WELL	API Number:	057-06264	Status:	IJ	Insp. Status:	IJ
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: 1. No evidence of any storm water controls to prevent sediment migration or tracking BMP's to prevent sediment from location being transported from location.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801670	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7099243