

From: Logan Frost <Logan.Frost@hilcorp.com>  
Sent: Tuesday, June 24, 2025 10:54 AM  
To: Tammy Jones <tajones@hilcorp.com>; Cameron Garrett <cgarrett@hilcorp.com>; Colby McKee <cmckee@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Scott Wagner <swagner@hilcorp.com>  
Subject: Re: ANDERSON 1R - INC - 719000107

Degraded soil was removed. Fresh gravel was also brought in. Exhaust system was repaired to prevent from further staining. If you have any questions, please let me know. Thanks!

-Logan Frost

Get [Outlook for iOS](#)

From: Tammy Jones <tajones@hilcorp.com>  
Sent: Friday, May 23, 2025 7:06:12 AM  
To: Logan Frost <Logan.Frost@hilcorp.com>; Cameron Garrett <cgarrett@hilcorp.com>; Colby McKee <cmckee@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Scott Wagner <swagner@hilcorp.com>  
Subject: RE: ANDERSON 1R - INC - 719000107

Inspection Photos attached

From: Tammy Jones  
Sent: Friday, May 23, 2025 7:06 AM  
To: Logan Frost <Logan.Frost@hilcorp.com>; Cameron Garrett <cgarrett@hilcorp.com>; Colby McKee <cmckee@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Scott Wagner <swagner@hilcorp.com>  
Subject: ANDERSON 1R - INC - 719000107

Today's Date: 5/23/2025						
Well Name:	ANDERSON 1R	Location:	Sec: 05	Twn: 032N	Rng: 006W	UL: M
API Number:	05.067.08746	Footage:	1193' FSL & 1190' FWL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0500	Logan Frost	
Meter #:	1540001		Pipeline:	RC		
INC Number:	719000107	Agency:	ECMC	Inspector:	Steve Labowskie	
Type of INC:	Written	Photos Required:	Yes	Due Date:	6/22/2025	
Issue of Concern:	Comment: OIL STAIN ON SIDE OF GAS ENGINE FORM PRIME MOVER MUFFLER SYSTEM					
	Corrective Action: CLEAN UP STAINED SOILS AND DISPOSE IN APPROVED MANNER RULE 1002.f TO PREVENT SITE DEGRADATION					
	Comment: OIL STAIN ON SIDE OF PRIME MOVER FROM ENGINE MUFFLER LEAK SEE LOCATION PICTURES					







