

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/10/2025

Submitted Date:

06/25/2025

Document Number:

718200042**FIELD INSPECTION FORM**Loc ID 427410 Inspector Name: Metz, Collin On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10773Name of Operator: FUNDARE RESOURCES OPERATING COMPANY LLCAddress: 5251 DTC PKWY STE 950City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Heibel, Krystal		krystal.heibel@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT

General Comment:**ECMC Environmental Field Inspection Report Summary**

This is an environmental inspection to determine progress on Spill ID 480281 and Remediation Project #30104. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 480281

Spill Name: Wildhorse 06-0634H

Remediation Project #: 30104

Facility ID: 427410

Reported Date of Discovery: 07/10/2021

Date of Inspection: 06/10/2025

Weather Conditions: Sunny 85-90 F

Spills are located within or adjacent to:

-Area Mapped in High Priority Habitat for Mule Deer Sever Winter Range and Mule Deer Winter Concentration Area

Current Site Status:

- Inadequate wildlife netting
- Leaking valve on wellhead
- Stained Soil

See attached corrective actions. A Form 19 - Supplemental is required.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment:	Stained soils observed at wellhead.			
Corrective Action:	Report spill or release of E&P waste or produced fluids. Remove free fluids and contact ECMC EPS staff per Rule 912.b. Control and contain spills/releases and clean up per Rule 912.a.			Date: 06/26/2025

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment:	Closed valve observed to be leaking fluids.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		
		Date:	06/26/2025

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 480281 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:Comment: Wildlife protection equipment (e.g. netting) installed at secondary containment is inadequate.

Corrective Action: Comply with Rule 902.b to install or repair wildlife protection equipment. The location will remain out of compliance until the corrective action has been resolved.

Date: 07/24/2025

Comment: _____Corrective Action: _____

Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation Project #30104 was created for the remediation of Spill ID 480281 pursuant to Rule 912 with Form 27 Initial Document Number 403389209 submitted on 05/31/2023. Form 27 Supplemental Document Number 403447946 submitted 06/28/2023 approved the closure requesting no further action for Remediation Project #30104. The last submitted Form 19 Supplemental Report Document Number 403232370 was received 11/16/2022. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure that was due 10/10/2021. Operator shall request closure of the Form 19 by checking the box for "Work proceeding under an approved Form 27 (Rule 912.c)."

Corrective Action: **Operator shall submit delinquent form(s) for this project.**

Date: 07/09/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404254883	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7110972
718200048	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7110964