

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9115 Entrance to location



Photo # 9131 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9118 Location



Photo # 9120 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9129 Location



Photo # 9141 Location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9144 NW corner of location



Photo # 9145 SW corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9146 SE corner of location



Photo # 9147 NE corner of location

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9151 Failure to minimize erosion & transport of sediment/insufficient BMP's



Photo # 9152 Failure to minimize erosion & transport of sediment/insufficient BMP's

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9153 Failure to minimize erosion & transport of sediment/insufficient BMP's



Photo # 9154 Failure to minimize erosion & transport of sediment/insufficient BMP's

Inspection/Audit Photos

Location: QB ENERGY OPERATING LLC SPECIALITY RESTAURANT E7OU PAD

Location ID: 334188

Date: 06/30/2025



Photo # 9164 Failure to minimize erosion & transport of sediment/insufficient BMP's



Photo # 9166 Failure to minimize erosion & transport of sediment/insufficient BMP's