

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404264594

Date Received:
07/07/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10608

Name of Operator: TALLGRASS WATER WESTERN LLC

Address: 370 VAN GORDON STREET

City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Scott Yount

316-322-3514

scott.yount@tallgrass.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718200038

Inspection Date: 06/10/2025

FIR Submit Date: 06/25/2025

FIR Status: _____

Inspected Operator Information:

Company Name: TALLGRASS WATER WESTERN LLC

Company Number: 10608

Address: 370 VAN GORDON STREET

City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: SWNE Sec: 30 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.812286 Longitude: -103.789600

FACILITY - API Number: 05-123-

-00

Facility ID: 487246

Facility Name: Horsetail Gathering (30 CPB)

Number: _____

Qtrqtr: SWNE Sec: 30 Twp: 10N Range: 57W Meridian: 6

Latitude: 40.812286 Longitude: -103.789600

CORRECTIVE ACTIONS:

1 CA# 205789

Corrective Action: Operator shall submit delinquent form(s) for this project.

Date: 07/09/2025

Response: CA COMPLETED

Date of Completion: 06/24/2025

Operator
Comment:

A supplemental form 19 was submitted requesting closure on 6/24/2025. The request for closure has been approved by the ECMC.

ECMC Decision: _____

ECMC
Representative:

2 CA# 205790

Corrective Action: Manage waste in compliance with Rule 913.b.(3) and ECMC Guidance 913.b.(5)B.i-v.

Date: 07/25/2025

Response: CA COMPLETED

Date of Completion: 07/02/2025

Operator Comment: Soil stockpile on site has been used to backfill the area where liquid gypsum was applied and to fill in areas of subsidence.

ECMC Decision:

ECMC
Representative:

3 CA# 205791

Corrective Action: Operator shall abide by the reclamation rules to minimize surface disturbances per the 1003.a.

Date: 07/25/2025

Response: CA COMPLETED

Date of Completion: 07/02/2025

Operator Comment: Subsidence of areas in previously backfilled excavations have been leveled.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The area will be re-seeded in the fall.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Yount

Signed:

Title: Sr. EHS Specialist

Date: 7/7/2025 8:56:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404268469	Photographs of Corrective Actions Taken
-----------	---

Total Attach: 1 Files