

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404264594

Date Received:  
07/07/2025

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10608  
Name of Operator: TALLGRASS WATER WESTERN LLC  
Address: 370 VAN GORDON STREET  
City: LAKEWOOD State: CO Zip: 80228

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Scott Yount</u>	<u>316-322-3514</u>	<u>scott.yount@tallgrass.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 718200038  
Inspection Date: 06/10/2025 FIR Submit Date: 06/25/2025 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TALLGRASS WATER WESTERN LLC Company Number: 10608  
Address: 370 VAN GORDON STREET  
City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: \_\_\_\_\_

Location Name: \_\_\_\_\_ Number: \_\_\_\_\_ County: \_\_\_\_\_  
Qtrqr: SWNE Sec: 30 Twp: 10N Range: 57W Meridian: 6  
Latitude: 40.812286 Longitude: -103.789600

FACILITY - API Number: 05-123-00 Facility ID: 487246

Facility Name: Horsetail Gathering (30 CPB) Number: \_\_\_\_\_  
Qtrqr: SWNE Sec: 30 Twp: 10N Range: 57W Meridian: 6  
Latitude: 40.812286 Longitude: -103.789600

CORRECTIVE ACTIONS:

**1** CA# 205789

Corrective Action: Operator shall submit delinquent form(s) for this project. Date: 07/09/2025

Response: CA COMPLETED Date of Completion: 06/24/2025

Operator Comment: A supplemental form 19 was submitted requesting closure on 6/24/2025. The request for closure has been approved by the ECMC.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 205790

Corrective Action: Manage waste in compliance with Rule 913.b.(3) and ECMC Guidance 913.b.(5)B.i-v.

Date: 07/25/2025

Response: CA COMPLETED

Date of Completion: 07/02/2025

Operator Comment: Soil stockpile on site has been used to backfill the area where liquid gypsum was applied and to fill in areas of subsidence.

ECMC Decision:

ECMC  
Representative:

**3** CA# 205791

Corrective Action: Operator shall abide by the reclamation rules to minimize surface disturbances per the 1003.a.

Date: 07/25/2025

Response: CA COMPLETED

Date of Completion: 07/02/2025

Operator Comment: Subsidence of areas in previously backfilled excavations have been leveled.

ECMC Decision:

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The area will be re-seeded in the fall.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Scott Yount

Signed:

Title: Sr. EHS Specialist

Date: 7/7/2025 8:56:27 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404264594	FIR RESOLUTION SUBMITTED
404268469	Photographs of Corrective Actions Taken

Total Attach: 2 Files