

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2025

Submitted Date:

07/02/2025

Document Number:

717900247**FIELD INSPECTION FORM**Loc ID 332204 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 200642Name of Operator: CIVITAS RESOURCES INCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	
,		Inspections@civiresources.com	All Inspections

General Comment:

This is an environmental inspection for Location ID 332204 Centennial Rein/CVR TB. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☒

Spills:

Type	Area	Volume		
In Containment: No				
Comment: No spills observed during inspection.				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 7/9/2025 Doc [#717900247]

Page 2 of 4

Location Construction

Location ID: 332204 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Tire rutting on site due to recent storm event. Operator to regrade site.

Corrective Action: Comply with Rule 1002.f.(2)

Date: 07/16/2025

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Environmental**Spills/Releases:**

Type of Spill:	Estimated Spill Volume:
Comment:	No spills or releases observed during inspection.
Corrective Action:	Date:
Reportable:	GPS: Lat Long
Proximity to Surface Water:	Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:	Owner Name:	GPS :	Lat	Long
------------------	-------------	-------	-----	------

Field Parameters:

Sample Location:	Comment:
------------------	----------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900248	photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134453