

Inspection Photos

06/06/2025

Operator: QB ENERGY OPERATING LLC
#10844

Location ID: 334855

Inspection Doc: 719200020

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



Photo 1: Photo taken from the central portion of the pad, showing an overview of the Location looking northwest and northeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



Photo 2: Photo taken from the central portion of the pad, showing an overview of the Location looking southeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



Photo 3: Photo taken from the western portion of the pad. Damaged, non-functional wattles were observed at the Location. Comply with Rule 606.a and remove debris.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



Photo 4: Photo shows fencing around a wellhead is insufficient to keep livestock out. Maintenance is advised.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



Photo 5: Photo shows a chipmunk burrow at the bottom of a tank battery. Maintenance is advised.

Inspection Photos

Operator Name: QB ENERGY OPERATING LLC #10844

Location ID: 334855



Jun 6, 2025 at 10:30:38 AM
Silt CO 81652
United States



Jun 6, 2025 at 10:47:14 AM
Silt CO 81652
United States

Photo 6: Photo shows sediment tracking across the pad. There are no BMPs in place for tracking/erosion at the site entrance. Stormwater and erosion control BMPs are missing or insufficient at the Location and access road. Comply with Rule 1002.f.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources