
MAIN PASS





9	Collar Locator	-1	LTEN	0	Amplified Amplitude (mV)	30	200	Variable Density	1200
0	Gamma Ray (GAPI)	200	0 (lb) 2000	0	Amplitude (mV)	100			

PIONEER
Pioneer Energy Services

MAIN PASS

PIONEER
Pioneer Energy Services

REPEAT PASS

Database File: bayswater triangle.db
Dataset Pathname: pass4
Presentation Format: cbl_dr
Dataset Creation: Thu May 23 07:33:20 2013 by Log SCH 120126
Charted by: Depth in Feet scaled 1:240



9	Collar Locator	-1	LTEN	0	Amplified Amplitude (mV)	30	200	Variable Density	1200
0	Gamma Ray (GAPI)	200	0 (lb) 2000	0	Amplitude (mV)	100			

PIONEER
Pioneer Energy Services

REPEAT PASS

Calibration Report

Database File: bayswater triangle.db
Dataset Pathname: pass5.1
Dataset Creation: Thu May 23 09:30:42 2013 by Calc 7.0 B1

Gamma Ray Calibration Report

Serial Number:	51013	
Tool Model:	probe 2.75	
Performed:	Thu Feb 23 11:03:07 2012	
Calibrator Value:	1400.0	GAPI
Background Reading:	26.8	cps
Calibrator Reading:	1120.0	cps
Sensitivity:	0.9000	GAPI/cps

Cement Bond Log Calibration Report

Serial Number:	050215		
Tool Model:	Probe		
Performed:	Sun Mar 03 10:58:23 2013		
Depth:	1065.76	ft	
Casing Diameter:	4.5	in	
	3' Spacing	5' Spacing	
Signal Zero:	-0.02	0	mV
Calibrated Amplitude:	62.1651	62.1651	mV
Reading at Signal Zero:	-0.00895996	0.040332	V
Reading in Free Pipe:	2.49832	1.98982	V
Gain:	33.2013	31.8879	
Offset:	0.202223	-1.2861	

PIONEER
Pioneer Energy Services

Company	BAYSWATER EXPLORATION &
Well	TRIANGLE 32-22
Field	WATTENBERG
County	WELD
State	COLORADO