


ANDROUICH W WELL
 COMPLAINT # 200236627



Invoice/Credit No.	28100561	Invoice Date	March 24, 2010
Terms	See Below		
Remit to	TestAmerica Laboratories, Inc. Dept 2314, P.O. Box 122314, Dallas, TX 75312-2314		

Bill to:
 Colorado Oil&Gas Conservation Commission
 Attn: Accounts Payable
 1120 Lincoln St.
 Suite 801
 Denver, CO 80203

Ship to:
 Colorado Oil&Gas Conservation Commission
 1120 Lincoln St.
 Suite 801
 Denver, CO 80203

P.O. Number	W.O. Number	Contract Number	Work Ordered by		
OE PHA 10000000010			Bob Chesson		
Job Description	Site Name	SDG Number	Invoice Contact		
See below			Bob Chesson		
Job No.	Job Description	Receipt Date	Quantity	Unit Price	Amount
	Method/Test Description				
J1099-1	24639 WCR6 Hudson, CO 80462	03/05/2010			
	SM 2320B - Alkalinity		1.00	20.00	20.00
	SM 2510B - Specific Conductance		1.00	20.00	20.00
	SM 2540C - Solids, Total Dissolved (TDS)		1.00	20.00	20.00
	300.0 - Anions - Cl, F, SO4, Br		1.00	72.00	72.00
	353.2 - Nitrogen, Nitrate-Nitrite		1.00	25.00	25.00
	6010B - Dissolved Metals		1.00	90.00	90.00
	8021B - BTEX+MTBE		2.00	60.00	120.00
	RSK-175 - Methane Only		1.00	125.00	125.00
	SM 4500 H+ B - pH		1.00	10.00	10.00
	Environmental Management Fee		1.00	25.10	25.10
<p>I HEREBY CERTIFY THAT I HAVE RECEIVED THE ARTICLES LISTED ABOVE, THAT I HAVE CAREFULLY INSPECTED, WEIGHED, COUNTED OR MEASURED THE COMMODITIES AND FOUND THEM IN GOOD CONDITION AND COMPLYING WITH THE SPECIFICATIONS GIVEN OR THAT THE SERVICES WERE SATISFACTORY, EXCEPT AS NOTED.</p> <p><i>[Signature]</i> 3/25/10 SIGNATURE DATE</p>					
Project Number	Client Number	Project Manager	Subtotal	\$527.10	
28002700	1355607	Lori Parsons			
Latest Sample Receipt Date	Latest Report Date	Phone Number	Total	\$527.10	
03/05/2010	03/24/2010	(303) 736-0100			

For proper credit, please include invoice number on all remittance.

TestAmerica Denver - 4955 Yarrow Street, Arvada, CO 80002

This invoice falls under TestAmerica Laboratories Inc. Standard T&C's of Net 30 Days unless superseded by another valid contract vehicle in place at the time these services were rendered.