

TIFFANY #2 P&A RISK ASSESSMENT

HUDSON OIL & METALS COMPANY

OPERATOR:
WELL NAME & NUMBER:
LOCATION:

TIFFANY #2
1,475' FSL & 990' FEL
SEC. 2, T 32 N, R 7 W
LA PLATA CO., CO

API NUMBER:
SPUD DATE:
PLUG DATE:

05-067-05172
10/07/1955
07/28/1956

NOTES:

All data used to create this wellbore schematic was obtained from documents on COGCC website.

Hole was filled with 10.6 ppg mud between plug #2 and plug #3; fluid density between plug #1 and plug #2 and between TD and plug #1 was not reported.

TOC for cement behind 7" casing was calculated assuming a 1.18 cuf/sx yield and a 70% cementing efficiency.

9/24/10: Site inspection conducted consisted of walking a 50' radius with a personal 4 gas monitor checking for seepage, no gas was found. The P&A marker not present. Vegetation noted as normal growth.

