

FORM
2

Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

APPLICATION FOR PERMIT TO:

1. Drill, Deepen, Re-enter, Recomplete and Operate

2. TYPE OF WELL

OIL GAS COALBED OTHER _____
SINGLE ZONE MULTIPLE ZONE COMMINGLE ZONE

Refilling
Sidetrack

Document Number:

400099277

Plugging Bond Surety

20090067

3. Name of Operator: WIEPKING-FULLERTON ENERGY LLC 4. COGCC Operator Number: 96340

5. Address: 4600 S DOWNING ST
City: ENGLEWOOD State: CO Zip: 80113

6. Contact Name: Jack Fincham Phone: (303)906-3335 Fax: (303)761-9067
Email: fincham4@msn.com

7. Well Name: Bubba-State Well Number: # 3

8. Unit Name (if appl): _____ Unit Number: _____

9. Proposed Total Measured Depth: 7900

WELL LOCATION INFORMATION

10. QtrQtr: SENW Sec: 20 Twp: 10S Rng: 55W Meridian: 6

Latitude: 39.165960 Longitude: -103.577670

Footage at Surface: 1980 FNL/FSL FNL 1980 FEL/FWL FWL

11. Field Name: Great Plains Field Number: 32756

12. Ground Elevation: 5195.19 13. County: LINCOLN

14. GPS Data:

Date of Measurement: 10/01/2010 PDOP Reading: 2.8 Instrument Operator's Name: Keith Westfall

15. If well is Directional Horizontal (highly deviated) **submit deviated drilling plan.**

Footage at Top of Prod Zone: FNL/FSL _____ FEL/FWL _____ Bottom Hole: FNL/FSL _____ FEL/FWL _____

Sec: _____ Twp: _____ Rng: _____ Sec: _____ Twp: _____ Rng: _____

16. Is location in a high density area? (Rule 603b)? Yes No

17. Distance to the nearest building, public road, above ground utility or railroad: 1980 ft

18. Distance to nearest property line: 660 ft 19. Distance to nearest well permitted/completed in the same formation: 1320 ft

20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
Cherokee	CHRK			
Marmaton	MRTN			
Morrow	MRRW			

21. Mineral Ownership: Fee State Federal Indian Lease #: 9365

22. Surface Ownership: Fee State Federal Indian

23. Is the Surface Owner also the Mineral Owner? Yes No Surface Surety ID#:

23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease? Yes No

23b. If 23 is No Surface Owners Agreement Attached or \$25,000 Blanket Surface Bon \$2,000 Surface Bond \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):
 Sec. 20: NW1/4, SE1/4, T10S, R55W

25. Distance to Nearest Mineral Lease Line: 660 ft 26. Total Acres in Lease: 320

DRILLING PLANS AND PROCEDURES

27. Is H2S anticipated? Yes No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling? Yes No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling? Yes No

30. If questions 27 or 28 are yes, is this location in a sensitive area (Rule 903)? Yes No **If 28, 29, or 30 are "Yes" a pit permit may be required.**

31. Mud disposal: Offsite Onsite

Method: Land Farming Land Spreading Disposal Facility Other: Backfill when dry

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bottom	Cement Top
SURF	12+1/4	8+5/8	24	300	250	300	0
1ST	7+7/8	5+1/2	17	7,900	300	7,900	6,500

32. BOP Equipment Type: Annular Preventer Double Ram Rotating Head None

33. Comments No conductor casing will be used.

34. Location ID: _____

35. Is this application in a Comprehensive Drilling Plan ? Yes No

36. Is this application part of submitted Oil and Gas Location Assessment ? Yes No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jack Fincham

Title: Agent Date: 10/11/2010 Email: fincham4@msn.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: David S. Nashin Director of COGCC Date: 11/13/2010

API NUMBER
 05 073 06432 00

Permit Number: _____ Expiration Date: 11/12/2012

CONDITIONS OF APPROVAL, IF ANY:

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

- 1) Provide 24 hour notice of MIRU to Craig Quint at 719-767-8939 or e-mail at craig.quint@state.co.us.
- 2) If production casing is set provide cement coverage to at least 200' above shallowest completed interval (200' above CHRK at a minimum), and stage cement Cheyenne/Dakota interval (4600'-3950' minimum). Run and submit CBL to verify cemented intervals.
- 3) If well is a dry hole set plugs at the following depths: 40 sks cement +/- 50' above the Atoka, 40 sks cement across any DST w/ show, 40 sks cement 50' below Cheyenne (4600' up), 40 sks cement 50' above top of Dakota (3950' up), 50 sks cement from 50' below surface casing shoe up into surface casing, 15 sks cement in top of surface casing, cut 4 ft below GL, weld on plate, 5 sks cement each in rat hole and mouse hole.

Attachment Check List

Att Doc Num	Name	Doc Description
2512825	SURFACE CASING CHECK	LF@2610987 2512825
400099277	FORM 2 SUBMITTED	LF@2601025 400099277
400099352	WELL LOCATION PLAT	LF@2601026 400099352
400099353	TOPO MAP	LF@2601027 400099353
400099354	OTHER	LF@2601088 400099354
400099355	30 DAY NOTICE LETTER	LF@2601089 400099355
400099507	PROPOSED BMPs	LF@2601090 400099507

Total Attach: 7 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	PERMITTING PASSED- JLV	11/11/2010 7:59:37 AM
Permit	Surface Restoration Bond on file with SLB, per Tim Kelly. Change Zone type to Multiple per Operator. JLV	11/11/2010 7:59:25 AM
Permit	Emailed Tim Kelly at SLB for verification of Surface Restoration Bond JLV	10/29/2010 11:33:24 AM

Total: 3 comment(s)

Error: Subreport could not be shown.