



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

REC'D EUSD

AUG 27 2010

OUR INVOICE 5.635

198360

(PO # 66878)

Date 8-17-10	Well Owner PTC	Well No. 34-18	Lease GUTTERSEN
County WELD	State COLORADO	Field	
Charge to ENSIGN US DRILLING	Charge Code		For Office Use Only
Address PO BOX 17805 (ENSIGN-5)			
City, State DENVER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1217	Code
Type of Job	Depth	Rt. 728	To
Surface 8 5/8" CSG 24#	Bottom of Surface	Rt. 718	To
Plug	Plug Landed @ 763	Ft. 718	Time On 0300
Production	Pipe Landed @ 718	Ft. 718	Time Off PLUG DOWN 0545

Reference No.	Description	Qty.	Meas.	Unit Price	Amount	
	Pump Truck Charge					
	Cement Near ✓	510	SKS			
	Poz. Mix					
	Calcium Chloride	3%				
	Gel % Flo-Cele 1/4 #Per Sack					
	Handling Charge					
	Hauling Charge					
	Additional Cement					
8 5/8'	CENTRALIZERS	3		70 "		
	CEMENT BASKET	1				
	GUIDE SHOE	1				
	BOX TAILGALLOCK	1				
		SLURRY VOL	1.16	FT ³ /SK		
	MIX RATE 4 BPM	SLURRY WT	15.2	PPG		
	DISP. RATE 5 BPM	TOTAL SLURRY VOL	107	BBL		
	PLUG LANDED @ 250 PSI	WATER TEMP	72 °F			
Remarks: FIREFLUSH w/ 20 BBL H ₂ O		Tax Reference Code		Sub Total		
DISPLACE w/ 44.5 BBL H ₂ O		State CO 2.9 %		Tax		
CIRCULATE 6 BBL CEMENT		Disc.		Total		
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1202		Pump Truck		78		
1217		Bulk Truck		78		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review.

Delivered By Joe, Josh KENNY

Received By [Signature]

Customer or His Agent