



02072150

CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198401

Date 9/4/10	Well Owner BOUWABA CREEK	Well No. 14-18	Lease Antelope
County Weld	State Colorado	Field	
Charge to Mud-Mixing Service	BOUWABA CREEK		Charge Code
Address P.O. Box 331 (Mud-Mixing)			For Office Use Only
City, State Englefield, TX 76037			
Pump Truck No. 1208	Code	Bulk Truck No. 1207	Code
Type of Job		Depth	ft. 435
Surface 8 5/8" Casing		Bottom of Surface	ft. 421
Plug		Plug Landed @ 4016	Time On 0400
Production		Pipe Landed @ 421	Time Off 0615

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Seal	300	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cole 1/4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	8 5/8" Cement Lines	2			
	" Cement Plug	1			
	" Air-Set	1			
	Rev. Line and Leak	1			
	Mixing Rate - 4 RPM / Dispensing Rate - 4 RPM				
	Slurry Vol. 1.15 CU FT / SK - Slurry wt 15.2 / PG				
	Total Slurry Vol 6.3 BBLs Cement				
	Landed Plug @ 200 PST / w/ 100 Tmp. 50% R				

Remarks: Pop-Flush w/ 15 BBLs H₂O	Tax Reference Code	Sub Total
Disperse w/ 25.5 BBLs H₂O	State CO 2.9 %	Tax
Circulate 5 BBLs Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1208		Pump Truck		46			
1207		Bulk Truck		46			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By **Justin, Steve & Dallas**

Received By

Justin 9/4/10
Customer or His Agent