



02054897

Andrews, David

From: Gibbs, Gailon J (GGibbs) [GGibbs@chevron.com]
Sent: Sunday, October 05, 2008 2:59 PM
To: Allred, Luke C. (LUCI); Ataushiyev, Mirambek; Bill_Kraft@co.blm.gov; Buddy Thompson; Clausen, John (je.clausen); Andrews, David; GGibbs@chevron.com; Gillespie, Frank E.; Hawkins, C. David (hawk@mssite01.ion.chevron.com); Ilavia, Phil [Independent]; Lee, Sang H. (Ihsa); Maser, Robert P [Contractor]; Medina, Dennis (DMED); DLPE@chevron.com; Roedell, Jeff W. (JRoedell) (JRoedell@mssite01.ion.chevron.com); MUZK@chevron.com; DAVID.VITELA@chevron.com; Walla, Andrew (AndyWalla); Wright, Craig (CWRI)
Subject: Kitti Fairfield A5 - API# 05-103-11010 - Update of upcoming operations. - 01
Follow Up Flag: Follow up D.A.
Flag Status: Red

Please be advised that as of this date we have cut the window in the 9-5/8" casing. It appears we have a piece of debris from the window, or a piece of junk on the bottom of the hole outside the window, which we are in the process of recovering. After this we plan to drill ahead to TD, which should be approx. a week to 10 days from now depending on the speed of our progress. Afterwards, we will prepare the hole for 7" casing and run and cement same with Schlumberger Pumping Services out of Vernal, Ut. This will be followed by drilling the Weber and leaving it as an open hole completion with a WSM in charge of operations. If additional info is needed, please call the numbers noted below. Respectfully,

Gailon J. Gibbs
Drill Site Manager
Chevron NA - MCABU
11111 S. Wilcrest, Houston Tx. 77099
Rig Site Office - 307-389-5789
Cell - 281-543-7820
ggibbs@chevron.com

PREP TO DRILL
"-02" SIDETRACK
TO THE WEBER FORMATION

D.A.