



CEMENTER'S WELL SERVICE, INC. P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198326

Date 8/22/2010	Well Owner MINERAL RESOURCES	Well No. Y36-8	Lease MAIN
County WELD	State COLORADO	Field	
Charge to MINERAL RESOURCES INC.	Charge Code		
Address 3109 35AVE BID1 (ETISIGN#14)	For Office Use Only		
City, State GREELEY, COLORADO 80634			
Pump Truck No. 1201	Code	Bulk Truck No. 1216/12	Code
Type of Job	Depth	Ft. 493	To
Surface 8 5/8" CSG 24"	Bottom of Surface	Ft. 478	To
Plug	Plug Landed @ 440	Ft.	Time On 0400
Production	Pipe Landed @ 478	Ft.	Time Off Plug Down 0630

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat <input checked="" type="checkbox"/> 100% EXCESS	340	SKS		6964 00
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele 1/4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement	100	SKS	14.60 SK	1460 00
	8 5/8" GUIDE SHOE	1			375 00
	" CEMENT BASKET	1			375 00
	" CENTRALIZERS	3		70 00	210 00
	" BAFFLE PLATE	1			200 00
	BOX THREAD LOCK	1			30 00
	MIXING RATE 4 BPM/DISP. RATE 5BPM				
	SLURRY VOL 1.18 FT ³ /SK - SLURRY WT 15.5, 2 PPG				
	TOTAL SLURRY VOL 92 BBLs CEMENT/LANDED PLUG @ 500 PSI				
Remarks:	FLUSH W/15 BBLs H ₂ O	Tax Reference Code	Sub Total		9614 00
	DISPLACE W/27.5 BBLs H ₂ O	State 2.9 %	Tax		278 81
	CIRCULATE 4 BBLs CEMENT	Disc.	Total		9892 81

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1201		Pump Truck		13			
1216/1214		Bulk Truck		13/13			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Jen/SAM/OSCAR Received By Don Ballman
Customer or His Agent