



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

195080

Date	4-10-06	Well Owner	Petroleum Management	Well No.	1F24	Lease	OK
County	Weld	State	CO	Field			
Charge to	Ensign USA Drilling				Charge Code		
Address	P.O. Box 17805 (716 11)				For Office Use Only		
City, State	Denver CO 80217						
Pump Truck No.	1703	Code		Bulk Truck No.	1218	Code	
Type of Job		Depth		Ft.	463	To	
Surface	854"	Bottom of Surface		Ft.	450	To	
Plug		Plug Landed @	435	Ft.		Time On	0800
Production		Pipe Landed @	450	Ft.		Time Off	PLUG DOWN 0900

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	31570			
	Poz. Mix				
	Calcium Chloride	300			
	Gel % Flo-Cele ^{1/4} #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	854 Cement 1705	3			
	" Cement Guide shoe	1			
	" Cement Basket	1			
	Mixing Rate 4BPM - Displacement Rate 6BPM				
	Slurry wt. 118 cc/l 15K slurry wt. 15.28%				

Remarks:	Pellish 4/22 1/2 Hls H2O	Tax Reference Code	Sub Total
	Displacement 27 1/2 Hls H2O	State %	Tax
	Cement 6 Hls Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1703	Pump Truck			1/4			
1218	Bulk Truck			1/4			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Rick H. Joe Rick K. Juits

Received By Raj Raj
Customer or His Agent