



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

DEC 16 2010

OUR INVOICE

198735

2

(P.O.# 92158)

Date 12/13/10	Well Owner PDC	Well No. 2 GD	Lease Anderson
County Weld	State Colorado		Field
Charge to ENSIGN US Drilling			Charge Code
Address 90. Box 17805 (ENSIGN "2")			For Office Use Only
City, State DENVER Colorado 80217			
Pump Truck No. 1208	Code	Bulk Truck No. 1214	Code
Type of Job		Depth	Fl. 698
Surface 8 5/8" 156-84"		Bottom of Surface	Fl. 688
Plug		Plug Landed @ 642	Fl. Time On 0420
Production		Pipe Landed @ 688	Fl. Time Off Plug Down 0815

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	490	SKS		
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cels 4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
8 5/8"	Centralizers	3			
"	Cement Basket	1			
"	Guide Shoe	1			
"	Baffle Plate	1			
"	Box Thread Lock	1			
	Mixing Rate - 4 BPM / Displacement Rate - 4 BPM				
	Slurry Vol - 1.18 CU FT/SK - Slurry WT 15.2 PPB / Water Temp 40° F				
	Total Slurry Vol 103 BBLS Cement / Landed Plug @ 590 PSI				

Remarks: Pre-Flush w/ 20 BBLS H ² O	Tax Reference Code	Sub Total
Displace w/ 40.5 BBLS H ² O	State CO 29 %	Tax
Circulate 4 BBLS Cement	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1208		Pump Truck		22	
1214		Bulk Truck		22	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is

Delivered By Justin Steve Dallas & James

Received By

Jim Stenon

Customer or His Agent