



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7289 • FAX (970) 353-7712

OUR INVOICE

198787

Rig 2

Date 12-26-10	Well Owner PDC	Well No. 2-AD	(PO# 95558)
County WELD	State COLORADO	Lease ANDERSON	
Charge to ENSIGN U.S. DRILLING		Field	
Address PO BOX 17805 (ENSIGN-2)		Charge Code	
City, State DENVER COLORADO 80217		For Office Use Only	
Pump Truck No. 1202	Code	Bulk Truck No. 1207	Code
Type of Job		Depth	R. 700
Surface 8 5/8" CSG-24H		Bottom of Surface	R. 690
Plug		Plug Landed @ 640	R. Time On 0745
Production		Pipe Landed @ 690	R. Time Off PLUG DOWN 1000

Reference No.	Description	Qty.	Meas.	Unit Price	Amount	
	Pump Truck Charge					
	Cement Seal ✓	490	SKS			
	Poz. Mix					
	Calcium Chloride	30%				
	Gel % Flo-Cele 1/4 Per Sack					
	Handling Charge					
	Hauling Charge					
	Additional Cement					
8 5/8"	CENTRALIZERS	2		70.00		
"	CEMENT BASKET	1				
"	GUIDE SHOE	1				
"	BAFFLE PLATE	1				
	BOX THREADLOCK	1				
MIX RATE 4	BPM	SLURRY VOL 1.18 FT ³ /K				
DISC RATE 5	BPM	SLURRY WT 15.2 PP10				
PLUG LANDED @ 600 PST		TOTAL SLURRY VOL 103 BBL			WATER TEMP	
Remarks: PRE FLUSH W/20 BBL H2O		Tax Reference Code		CEMENT		
DIS PLACE W/41 BBL H2O		State CO 2.9%		Sub Total		
CIRCULATE 6 BBL CEMENT		Disc.		Tax		
				Total		
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1202		Pump Truck		38		
1207		Bulk Truck		38		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review.

Delivered By **JOE, JOSH, KERRY, EVAN**

Received By

Customer or His