



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 338220 • GREELEY, CO 80633 • (970) 353-7289 • FAX (970) 353-7712

OUR INVOICE

198864

(P.O.# 100965)

Date 1-20-11	Well Owner PDC	Well No. 2TD	Lease LEFFLER
Country WELD	State COLORADO	Field	
Charge to ENSIGN US DRILLING	Charge Code		
Address PO BOX 17805 (ENSIGN)-21	Per Office Use Only		
City, State DENVER COLORADO 80217			
Pump Truck No. 1202	Code	Bulk Truck No. 1218	Code
Type of Job	Depth	R. 680	To
<input checked="" type="checkbox"/> Surface 8 5/8" CSD 24#	Bottom of Surface	R. 670	To
Plug	Plug Landed @ 625	Pt. Time On 0400	
Production	Pipe Landed @ 670	Pt. Time Off PLUG DOWN 0600	

Reference No.	Description	Qty.	Meas.	Unit Price		
	Pump Truck Charge					
	Cement Mast ✓	470	SKS			
	Pos. Mix					
	Calcium Chloride	3%				
	Gel % Flo-Calc 1/4 #Per Sack					
	Handling Charge					
	Hauling Charge					
	Additional Cement					
8 5/8"	CENTRALIZERS	3		70.00		
"	CEMENT BASKET	1				
"	GUIDE SHOE	1				
"	RAFFLE PLATE	1				
	BOX THREADLOCK	1				
	MIX RATE 45PPH	SLURRY VOL 10.16	FT ³ /SK	WATER TEMP		
	DISP RATE 5BPM	SLURRY WT 15.2	PPG			
	PLUG LANDED @ 900 PSI	TOTAL SLURRY VOL 98.5	BBL CEMENT			
Remedy	FEELISH W/20 BBL H2O	Tax Reference Code	Sub Total			
	DISPLCE W/40 BBL H2O	State CO 2.9 %	Tax			
	CIRCULATE 5 BBL CEMENT	Disc.	Total			
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1202		Pump Truck		18		
1218		Bulk Truck		18		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review.

Delivered By JOE, JOSH, KERRY, EVAN

Received By

Jim Sklar
Customer or His