

Geologist Information

General: Existing location, 10 new wells, 4 existing.
Ownership: Fee Surface, Split Minerals
SUA Status: Existing, needs to be amended to include new wells.
Spacing Units: 1 - Sec 36
Adjacent Owners: BLM



BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT

Plan of Development

Access: Existing access will be used.
Drilling: Efficiency rig.
Cuttings: Will be buried in existing trench for the 10 wells drilled from pad.
SIMOPS: Cuttings from the RWF 33-36 and RWF 32-36 will also be buried on this pad.
Completion: Yes.
Flowback: Frac from the RWF 33-36. Will run 3 - 4.5" surface frac lines to this pad.
Prod Equip: Flow back to the RWF 33-36.
Pipeline: Tanks and production equipment to be set in the SW corner.
ETC dedicated gas. Existing gas and water lines are adequate.

Legend

- | | |
|--------------------------------------|---|
| ● Production Gas Well | ----- Property Boundary |
| ■ Proposed Production Equipment Area | --- Existing Surface Frac Line |
| — Existing Production Equipment | --- Proposed Surface Frac Line |
| --- Existing Limit of Disturbance | — Road |
| --- Proposed Daylight Line | Parcel Ownership (from Garfield County) |
| --- Proposed Pad or Pit | |
| --- Existing Fence | |

Williams Production RMT

GV 15-36 Plan of Development
T6S R94W, Section 36



Date Prepared: April 28, 2011