



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

199428

(Po^d 117912)

Date	3/28/2011	Well Owner	PDC	Well No.	42-32D	Lease	moody
County	WELD	State	COLORADO	REC'D EUSD		Fight	
Charge to	ENSTAD U.S. DRILLING					Charge Code	
Address	P.O. BOX 17805 (ENSTAD # 5)					For Office Use Only	
City, State	DENVER, COLORADO 80217						
Pump Truck No.	1201	Code		Bulk Truck No.	1207/12	Code	
Type of Job				Depth		R.	946
Surface	8 5/8" CSG - 24"			Bottom of Surface		R.	936
Plug				Plug Landed @	901	R.	Time On 0900
Production				Pipe Landed @	936	R.	Time Off 1050

Reference No.	Description	Qty.	Mens.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	660	SKS		
	Poz. Mix				
	Calcium Chloride	390			
	Gel % Flo-Cels 1/4# Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	MIXING RATE 4BPM				
	DISP. RATE 5BPM				
	SLURRY VOL 1.18 CUFT/SK				
	SLURRY WT 14.3-15.1 PPG				
	TOTAL SLURRY VOL 138.7 BALS CEMENT				
	LANDING PLUG @ 900 PST				
	WATER TEMP 45				

Remarks:	Tax Reference Code	Sub Total
PRE-FLUSH W/ 30 BALS H ₂ O		
DISPLACE W/ 57 BALS H ₂ O	State CO 2.9 %	Tax
CIRCULATE 4 BALS CEMENT	Disc.	Total

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming
1201		Pump Truck		45	
1207/12		Bulk Truck		45/45	

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject

Delivered By JIM/ADAM/OSCAR/STEVE

Received By

Customer or His Agent