

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-2109

SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form.) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

02121242

RECEIVED

JUN 26 2011

COGCC/Rifle Office

1. OGCC Operator Number: 34720	4. Contact Name John Gordon	Complete the Attachment Checklist
2. Name of Operator: Gordon Engineering, Inc.	Phone: (970) 245-1958	
3. Address: P.O. Box 3525	Fax: (970) 242-5106	OP OGCC
City: Grand Junction State: CO Zip: 81502		
5. API Number 05-077-08524	OGCC Facility ID Number	Survey Plat
6. Well/Facility Name: Alta Federal	7. Well/Facility Number 23-1	Directional Survey
8. Location (Qtr/Qtr, Sec, Twp, Rng, Meridian): SW1/4SW1/4 (608'FWL, 1119' FSL), Sec. 23, T9S, R97W		Surface Eqmpt Diagram
9. County: Mesa	10. Field Name: Shire Gulch/Horseshoe Canyon	Technical Info Page
11. Federal, Indian or State Lease Number: C-12731		Other

General Notice

<input type="checkbox"/> CHANGE OF LOCATION: Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)	
Change of Surface Footage from Exterior Section Lines:	<input type="checkbox"/> FNU/FSL <input type="checkbox"/> FEU/FWL
Change of Surface Footage to Exterior Section Lines:	<input type="checkbox"/> <input type="checkbox"/>
Change of Bottomhole Footage from Exterior Section Lines:	<input type="checkbox"/> <input type="checkbox"/>
Change of Bottomhole Footage to Exterior Section Lines:	<input type="checkbox"/> <input type="checkbox"/> attach directional survey
Bottomhole location Qtr/Qtr, Sec, Twp, Rng, Mer	
Latitude	Distance to nearest property line
Longitude	Distance to nearest bldg, public rd, utility or RR
Ground Elevation	Distance to nearest lease line
	Is location in a High Density Area (rule 603b)? Yes/No
	Distance to nearest well same formation
	Surface owner consultation date:
GPS DATA:	
Date of Measurement 11/20/08 PDOP Reading 6 Instrument Operator's Name DH Survey	
<input type="checkbox"/> CHANGE SPACING UNIT	<input type="checkbox"/> Remove from surface bond
Formation Formation Code Spacing order number Unit Acreage Unit configuration	Signed surface use agreement attached
<input type="checkbox"/> CHANGE OF OPERATOR (prior to drilling):	<input type="checkbox"/> CHANGE WELL NAME
Effective Date:	From:
Plugging Bond: <input type="checkbox"/> Blanket <input type="checkbox"/> Individual	To:
	Effective Date:
<input type="checkbox"/> ABANDONED LOCATION:	<input type="checkbox"/> NOTICE OF CONTINUED SHUT IN STATUS
Was location ever built? <input type="checkbox"/> Yes <input type="checkbox"/> No	Date well shut in or temporarily abandoned:
Is site ready for inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	Has Production Equipment been removed from site? <input type="checkbox"/> Yes <input type="checkbox"/> No
Date Ready for Inspection:	MIT required if shut in longer than two years. Date of last MIT
<input type="checkbox"/> SPUD DATE:	<input type="checkbox"/> REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)
<input type="checkbox"/> SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK *submit cbl and cement job summaries	
Method used Cementing tool setting/perf depth Cement volume Cement top Cement bottom Date	
<input type="checkbox"/> RECLAMATION: Attach technical page describing final reclamation procedures per Rule 1004.	
Final reclamation will commence on approximately <input type="checkbox"/> Final reclamation is completed and site is ready for inspection.	

Technical Engineering/Environmental Notice

<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Report of Work Done	
Approximate Start Date: 06/27/2011	Date Work Completed:	
Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)		
<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Disposal
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested	<input type="checkbox"/> Status Update/Change of Remediation Plans
<input type="checkbox"/> Casing/Cementing Program Change	<input checked="" type="checkbox"/> Other: TA	for Spills and Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: John I. Gordon Date: 06/26/2011 Email: johnngordon1gordon@yahoo.comPrint Name: John I. Gordon Title: PresidentCOGCC Approved: [Signature] Title: EIT 3 Date: 6/28/11


CONDITIONS OF APPROVAL, IF ANY:

ALTA FEDERAL #23-1
TEMPORARY ABANDONMENT PROCEDURE

Discussion: A workover has been started to perform an MIT evaluation of the casing on the well. See WBD which is enclosed. During the workover, the tubing as shown and the packer as shown were removed from the well. An attempt was made to return to bottom with a bit and casing scraper and the assembly stopped at a depth of approximately 1960'. Since that time, several attempts have been made to get into the hole with tubing with little success. Several additional attempts to get into the hole will be made and if successful, the following temporary abandonment procedure will be done.


1. Set cement plug across bottom perforations at 7433'-7839' using 50 sacks of Class "G" cement across the perforation at 7433'-7839'. Anticipated fill will be in excess of 650' in the 4-1/2" 11.6# casing.
2. Tag plug if required.
3. Pull out of hole to approximately 4500' and set 20 sack Class "G" balanced cement plug at 4250'-4500'.
4. Pull out of hole to approximately 1700' and set 30 sack Class "G" balanced cement plug at 1450'-1600'.
5. Tag plug if required.
6. Set cement retainer at 300' and cement squeeze with 50 sacks of Class "G" cement. Leave 5 sacks on top of retainer.
7. Secure top of well by installing upper tree assembly.

NOTE: See attached Proposed WBD.



PROPOSED TA
Alta Federal #23-1
 SW1/4SW1/4 Sec. 23, T9S, R97W (608' FWL, 1119' FSL)
 Mesa County, Colorado
 As of 04-06-11 JIG
 API Number: 05-077-08524

RECEIVED
 JUN 26 2011
 COGCC/Rifle Office



Alta Federal #23-1
SW1/4SW1/4 Sec. 23, T9S, R97W (608' FWL, 1119' FSL)
Mesa County, Colorado
As of 04-06-11 -JIG
API Number: 05-077-08524

RECEIVED
JUN 26 2011
COGCC/Rifle Office

