



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198645

(P.O.# 86547)

Date 11/14/2010	Well Owner SYNERGY RESOURCES	Well No. 14-15D	Lease RBF
County WELD	State COLORADO	Field	
Charge to ENSTIG U.S. DRILLING	Charge Code		For Office Use Only
Address P.O. BOX 17805 (ENSTIG #33)			
City, State DENVER, COLORADO 80217			
Pump Truck No. 1201	Code	Bulk Truck No. 1207	Code
Type of Job	Depth	Ft. 476	To
Surface 8 5/8" CSG 24"	Bottom of Surface	Ft. 466	To
Plug	Plug Landed @ 422	Ft.	Time On 1000
Production	Pipe Landed @ 466	Ft.	Time Off Plug Down 1315

Reference No.	Description	Qty.	Meas.	Unit Price	Amount		
	Pump Truck Charge						
	Cement Neat ✓	370	SKS		7402	00	
	Poz. Mix						
	Calcium Chloride	3%					
	Gel % Flo-Cele 1/4 #Per Sack						
	Handling Charge						
	Hauling Charge						
	Additional Cement						
8 5/8	GUIDE SHOE	1			300	00	
"	CEMENT BASKET	2		300 ⁰⁰	600	00	
"	CENTRALIZER	1		60	60	00	
"	BAFFLE PLATE	1			200	00	
	BOX THREAD LOCK	1			30	00	
	MIXING RATE 4 BPM / DISPLACE RATE 5 BPM						
	SLURRY VOL 1.18 CU FT 3/4 SK - SLURRY WT 15.0 - 15.2 PPG						
	TOTAL SLURRY VOL TL 5 BBLS CEMENT / PLUG LANDED @ 640 PSI						
Remarks: PRE-FLUSH w/ 10 BBLS H ² O		Tax Reference Code		Sub Total		8592 00	
DISPLACE w/ 26.5 BBLS H ² O		State CO 2.9 %		Tax		249 17	
CIRCULATE 5 BBLS CEMENT		Disc.		Total		8841 17	
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1201		Pump Truck		17			
1207		Bulk Truck		17			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Jim/SAM/OSCAR/TRAVERS

Received By Jerry Rogers
Customer or His Agent