



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

198466

(PO# 82151)

Date 11/2/2010	Well Owner SYNERGY RESOURCES	Well No. 23-150	Lease RBF
County WELD	State COLORADO	Field	
Charge to ENSTON U.S. DRILLING	Charge Code		For Office Use Only
Address P.O. BOX 17805 (ENSTON#33)			
City, State DENVER COLORADO 80217			
Pump Truck No. 1201	Code	Bulk Truck No. 128	Code
Type of Job	Depth	Ft. 472	To
Surface 8 5/8" CSG 24"	Bottom of Surface	Ft. 461	To
Plug	Plug Landed @ 417	Ft.	Time On 2300
Production	Pipe Landed @ 461	Ft.	Time Off Plug Down 0200

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓ 100% EXCESS	330	SKS		6818 00
	Poz. Mix				
	Calcium Chloride	390			
	Gel % Flo-Cele 1/4 #Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement	40	SKS	14.60	584 00
	8 5/8" GUIDE SHOE	1			300 00
	" CEMENT BASKET	2		300 00	600 00
	" CENTRALIZER	2		60 00	120 00
	" BAFFLE PLATE	1			150 00
	BOX THREAD LOCK	1			30 00
	MIXING RATE 4 BPM/DISP RATE 5 BPM				
	SLURRY VOL 1.18 CU FT/SK - SLURRY WT 14.8-15.0 PPG				
	SLURRY VOL 7.5 BBLS CEMENT / PLUG LANDED @ 680 PSI				
Remarks:	PRE-FLUSH W/15 BBLS H2O	Tax Reference Code	Sub Total	8602	00
	DISPLACE W/26.5 BBLS H2O	State CO 2.9 %	Tax	249	46
	CIRCULATE 5 BBLS CEMENT	Disc.	Total	8851	46

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1201		Pump Truck		33			
128		Bulk Truck		33/33			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By **Jim/SAM/TRAVIS**

Received By **Ephraim Isaac**
Customer or His Agent