



**LAMP RYNEARSON
& ASSOCIATES**
ENGINEERS | SURVEYORS | PLANNERS

4715 Innovation Drive, Suite 100
Fort Collins, Colorado 80525
[P] 970.226.0342
[F] 970.226.0879
www.LRA-Inc.com

September 30, 2011

David Neslin
Colorado Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, Colorado 80203

**Re: Request for 318A Surface Location Exception
Wells: See Enclosed Exhibit A
Township 5 North, Range 66 West, 6th PM
Surface Location: SE 1/4 of the SW 1/4, Section 2
Weld County, Colorado**

Dear Mr. Neslin:

Mineral Resources, Inc. is planning to drill the referenced wells outside of the designated GWA drilling window and hereby requests an exception to Rule 318A.a. The locations are being permitted as an exception location. The wells will be drilled outside of the GWA window in an effort to minimize surface disturbance and improve drilling efficiency by utilizing a single well pad for multiple wells.

Mineral Resources, Inc. respectfully requests that the COGCC approve the requested exception location and Application for Permit to Drill for the referenced wells. Thank you for your attention to this matter. Please contact Lamp Rynearson and Associates at (970) 226-0342 with any questions or concerns.

Sincerely,

LAMP, RYNEARSON & ASSOCIATES, INC.

Daniel Hull, PE
Designated Agent
Mineral Resources, Inc.

ddh/jz

enclosures

EXHIBIT A
Well Names for Surface Well Location Exception Request

Bestway 6-2-2

Ditch 5-1-2

Edmoor 6-6-2

Franklin Park 2-6-1

Johnson 5-3-2

Pheasant 5 2-2-2

Ruyle 7-3-2

Stoney 7-1-2

Westmoor 5 2-6-2