



State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303) 894-2100 Fax: (303) 894-2109



FOR OGCC USE ONLY

RECEIVED
10/10/2011

ACCIDENT REPORT

As required by Rule 602.b.

Report taken by:

DESCRIPTION OF ACCIDENT (Please be as specific as possible)

Name of Operator: Encana Oil and Gas
Date of Incident: October 1, 2011
Type of Facility (well, tank battery, flow line, pit): Patterson 326 Drill Rig
Well Name & Number: Benzel at F25NWB location
API Number: 05045207790000
Connect to Accident (land owner, royalty owner, etc.): Benzel

Location	
County: Garfield	
Field Name: Mamm Creek	
QtrQtr: SW 1/4 NW 1/4	Section: 25
Township: T6S	Range: R93W
Meridian: 6th	

Provide a detailed description of the accident, problem, and cause (equipment failure, human error, etc.):

Drill rig worker, while pulling apart 4" hose from a camlock fitting connection, was struck in the mouth when the hose came loose with a whipping action. The result was 3 chipped teeth with medical aid designation.

Other Notifications

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact Person	Response

Accident Tracking No: I2011-01598__