



EnCana Marketing (USA) Inc.

370 17th Street
Suite 1700
Denver, CO 80202

tel: (303) 623-2300
fax: (303) 623-2400
www.encana.com

October 28, 2011

Mr. David Neslin
Colorado Oil & Gas Conservation Commission
1120 Lincoln Street, Suite 801
Denver, CO 80203

Re: Davis 2A-9H
Niobrara New Drill
Township 2 North, 66 West, 6th PM
Section 9: 1966' FNL/ 519' FWL (Surface Location)
Section 9: 2089' FNL/ 996' FWL (Beginning of Lateral)
Section 4: 2190' FSL/ 987' FWL (End of Lateral)

Dear Mr. Neslin:

Encana Oil & Gas (USA) Inc. ("Encana") is planning to drill the captioned well in accordance with the provisions of COGCC Rule 3189A.e.

Encana's proposed wellbore spacing unit consists of the NW4 of Section 9 & SW4 of Section 4 T2N-66W, creating a 320-acre wellbore spacing unit, therefore Encana hereby attests that no notice letters are required under COGCC Rule 318A.e.(6)

Enclosed is a copy of the map illustrating the proposed wellbore spacing unit to assist you in your review and approval of Encana's proposed APD for the captioned well.

Thank you for your assistance in this matter. If you have any questions or comments, please contact me at (720)-876-5288.

Very truly yours,
ENCANA OIL & GAS (USA) INC.

A handwritten signature in black ink, appearing to read "Nick Curran", written over a horizontal line.

Nick Curran
Permitting Agent


Davis 2A-9H
SWNW SEC 9 T2N-R66W

Purple outline = Proposed 320 acrespacing unit in the NW4 OF SEC 9
& SW4 of SEC. 4 (2n-66w)

Green dashed outline = NW4 (location of surface)

Bottom hole located at 2190' FSL & 987' FWL

This half-section has less than 16 bottom hole wells producing from the
Niobrara formation.



○ = Surface location

● = Bottom hole location