

02121384

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-2109



RECEIVED JAN 18 2012 COGCC/Rifle Office

SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form.) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

1. OGCC Operator Number: 96850
2. Name of Operator: Williams Production RMT Company LLC
3. Address: 1001 17th Street, Suite 1200
4. Contact Name: Greg Davis
5. API Number: 05-045-19434-00
6. Well/Facility Name: Puckett
7. Well/Facility Number: GM 44-31
8. Location: NWSE 31-T6S-96W
9. County: Garfield
10. Field Name: Grand Valley
11. Federal, Indian or State Lease Number:

Table with columns for Survey Plat, Directional Survey, Surface Eqmpt Diagram, Technical Info Page, and Other. Includes checkboxes for OP and OGCC.

General Notice

CHANGE OF LOCATION: Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)
Change of Surface Footage from Exterior Section Lines:
Change of Surface Footage to Exterior Section Lines:
Change of Bottomhole Footage from Exterior Section Lines:
Change of Bottomhole Footage to Exterior Section Lines:
Bottomhole location Qtr/Qtr, Sec, Twp, Rng, Mer
Latitude
Longitude
Ground Elevation
Distance to nearest property line
Distance to nearest lease line
Distance to nearest well same formation
Distance to nearest bldg, public rd, utility or RR
Is location in a High Density Area (rule 603b)?
Surface owner consultation date:

GPS DATA:
Date of Measurement
PDOP Reading
Instrument Operator's Name

CHANGE SPACING UNIT
Formation
Formation Code
Spacing order number
Unit Acreage
Unit configuration
Remove from surface bond
Signed surface use agreement attached

CHANGE OF OPERATOR (prior to drilling):
Effective Date:
Plugging Bond: Blanket Individual
CHANGE WELL NAME
From:
To:
Effective Date:
NUMBER

ABANDONED LOCATION:
Was location ever built?
Is site ready for inspection?
Date Ready for inspection:
NOTICE OF CONTINUED SHUT IN STATUS
Date well shut in or temporarily abandoned:
Has Production Equipment been removed from site?
MIT required if shut in longer than two years. Date of last MIT

SPUD DATE:
REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)

SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK
Method used
Cementing tool setting/perf depth
Cement volume
Cement top
Cement bottom
Date
*submit cbl and cement job summaries

RECLAMATION:
Attach technical page describing final reclamation procedures per Rule 1004.
Final reclamation will commence on approximately
Final reclamation is completed and site is ready for inspection.

Technical Engineering/Environmental Notice

Notice of Intent
Approximate Start Date:
Report of Work Done
Date Work Completed:

Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)

Intent to Recomplete (submit form 2)
Change Drilling Plans
Gross Interval Changed?
Casing/Cementing Program Change
Request to Vent or Flare
Repair Well
Rule 502 variance requested
Other: Cement Squeeze
E&P Waste Disposal
Beneficial Reuse of E&P Waste
Status Update/Change of Remediation Plans
for Spills and Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Greg Davis Date: 9/21/11 Email: Greg.J.Davis@Williams.com
Print Name: Greg Davis Title: Supervisor Permits

COGCC Approved: [Signature] Title: NWA Engineer Date: 1/18/12
CONDITIONS OF APPROVAL, IF ANY:

TECHNICAL INFORMATION PAGE



FOR OGCC USE ONLY

1. OGCC Operator Number:	96850	API Number:	05-045-19434-00
2. Name of Operator:	Williams Production RMT Company LLC OGCC Facility ID #		
3. Well/Facility Name:	Puckett	Well/Facility Number:	GM 44-31
4. Location (QtrQtr, Sec, Twp, Rng, Meridian):	NWSE Sec 31 T6S-R96W		

RECEIVED
 JAN 18 2011
 COGCC/Rifle Office

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. DESCRIBE PROPOSED OR COMPLETED OPERATIONS



Williams Production RMT Co.
 Flow Test / Swabbing procedure (Squeeze procedure for MV4)

Wellname: GM 44-31
 Date: 9/21/11
 Field: Grand Valley

Prepared By: Kristin Trahan
 Cell phone: 303-482-7901

Purpose: Reduce water production rate by squeezing off MV4

Well Information:

API Number:	05-045-194340000
Production Casing:	4-1/2" 11.6# E-80
Shoe Depth:	7,099 ft
Float Collar Depth:	7,069 ft
Surface Casing Depth:	1,098 ft
Top of Mesaverde:	3,980 ft
Top of Gas:	5,119 ft
Correlate Log:	Baker CBL - 1/8/2011
Max pressure:	7,000 psi

Well History:

- This well was completed in February 2011 and put on final sales 5/24/11. It is currently making 270 bbls/day
 - 6 stages were completed. Top perf is 5,403 ft (284 ft below TOG).

Proposed Procedure:

- Contact Ryan Olson and arrange to bleed down well and remove automation equipment prior to moving in service unit.
- MIRU workover unit
 Tag fill and note depth in OW
 Pull tubing out of the hole, note depth of any scale or visible holes in tubing in OW.
 RIH with tubing and set CIBP at 5,590 ft to isolate the MV4 from the rest of the well.
- RIH with wireline and set cement retainer at 5,300 ft (100 ft above top perf)
 RIH with tubing and circulate right above the retainer, sting into retainer at 5,300 ft and perform brief injection rate test to confirm ability to squeeze perforations
- MIRU HES Cementing unit
 Establish injection with freshwater and braden head valve closed
 Pump 200 sx 17.0 ppg cement with 0.5% CFR-3
 Stage last two bbis of cement
 Unseat packer and POOH ~60' to reverse circulate any remaining cement in tubing
 WOC
- RIH drill cement/retainer and clean out to CBP at 5,590 ft
 Pressure test casing to 1,000 psi
 RIH and clean out to float collar
 Land tubing at 6,788 ft
 RDMO Workover unit