

**From:** [Stanczyk, Jane](#)  
**To:** [Yokley, Bill](#)  
**Subject:** FW: Tubbs #1  
**Date:** Thursday, February 09, 2012 1:27:05 PM

---

Bill – please PDF this email

Jane Stanczyk  
Permit Supervisor  
Colorado Oil and Gas Conservation Commission  
Phone:(303) 894 2100 ext.5119  
FAX: (303) 894 2105  
E-mail: [jane.stanczyk@state.co.us](mailto:jane.stanczyk@state.co.us)

---

**From:** Paul Thompson [mailto:[paul@walsheng.net](mailto:paul@walsheng.net)]  
**Sent:** Friday, December 16, 2011 10:57 AM  
**To:** Stanczyk, Jane  
**Cc:** Pat Oldham  
**Subject:** Tubbs #1

Jane, When we first started operating this well we tried to clean out the wellbore to PBTD. Despite several acid jobs we were never able to clean out the Dakota perms. We came back up hole, set a pump jack, and pumped water from the Mesa Verde formation. Since the wellbore is plugged with scale below the Mesa Verde and we know that the Dakota is under water from the pumping experience, I don't see how the Dakota could ever produce. We have been reporting all the production from the Mesa Verde as I believe our predecessors were. Paul Thompson