



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200060

(PO.#161792)

Date 9/17/2011	Well Owner SYNERGY RESOURCES	Well No. 11-21-D	Lease CLETCHER
County WELD	State COLORADO	Field	
Charge to ENSIGN U.S. DRILLING			Charge Code
Address P.O. BOX 17805 (ENSIGN #33)			For Office Use Only
City, State DENVER, COLORADO 80217			
Pump Truck No. 1201	Code	Bulk Truck No. 1218	Code
Type of Job	Depth	Ft. 613	To
Surface 8 5/8" CSG 24"	Bottom of Surface	Ft. 603	To
Plug	Plug Landed @ 561	Ft.	Time On 0030
Production	Pipe Landed @ 603	Ft.	Time Off PLUG DOWN 0115

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	430	SKS		
	Poz. Mix				
	Calcium Chloride	390			
	Gel % Flo-Cele 1/4# Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
	8 5/8" GUIDE SHOE	1			
	" CEMENT BASKET	1			
	" CENTRALIZERS	3		7000	
	" BAFFLE PLATE	1			
	BOX THREAD LOCK	1			
	MIXING RATE 4BPM / DISP RATE 5BPM				
	SLURRY VOL 1.18 CUFT/SK - SLURRY WT 14.8-15.0 PPG				
	TOTAL SLURRY VOL 90.3 BBLS CEMENT / PLUG LANDED @ 850				
PRE-FLUSH W/20 BBLS H2O	Tax Reference Code	Sub Total			
DISPLACE W/35.6 BBLS H2O	State CO29 %	Tax			
CIRCULATE 6 BBLS CEMENT	Disc.	Total			

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1201		Pump Truck		45		
1218		Bulk Truck		45		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By **JIM/ADAM/CHRIS**

Received By **Ephraim Isaacs**
Customer or His Agent