



CEMENTER'S WELL SERVICE, INC.
P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200277

(D.O.# 177499)

Date 11-18-11	Well Owner SYNERGY RESOURCES	Well No. 14-26 D	Lease LEFFLER
County WELD	State COLORADO	Field	
Charge to ENSTON US DRILLING	Charge Code		
Address P.O. BOX 17805 (ENSTON #33)	For Office Use Only		
City, State DENVER COLORADO 80217			
Pump Truck No.	Code	Bulk Truck No.	Code
Type of Job	Depth	Fl. 4168	To
<u>Surface</u> 8 5/8" CSG 741#	Bottom of Surface	Fl. 4158	To
Plug	Plug Landed @ 415	Fl. Time On 0115	
Production	Pipe Landed @ 4158	Fl. Time Off PUG DOWN 0330	

Reference No.	Description	Qty.	Meas.	Unit Price	Amount
	Pump Truck Charge				
	Cement Neat ✓	330	SKS		7100 50
	Poz. Mix				
	Calcium Chloride	3%			
	Gel % Flo-Cele 1/4#Per Sack				
	Handling Charge				
	Hauling Charge				
	Additional Cement				
8 5/8"	CENTRALIZERS	3		70.00	210 00
"	CEMENT BASKET	1			350 00
"	GUIDE SICE	1			350 00
"	BAFFLE PLATE	1			150 00
	BOX THREADLOCK	1			30 00
	MIX RATE 4 RPM	SLURRY VOL 1.18	FT ³ /SK	WATER TEMP 38 OF	
	DISP RATE 5 RPM	SLURRY WT 15.2	PPG		
	PUG LANDING 700 PSI	TOTAL SLURRY VOL 69.3	BBL CEMENT		
Remarks: TREEFLUSH W/15 BBL H ₂ O	Tax Reference Code	Sub Total			8190 50
DISPLNCE W/26.3 BBL H ₂ O	State CO 2.9 %	Tax			237 52
CIRCULATE 3 BBL CEMENT	Disc.	Total			8428 02

Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other	Total Mileage
1202		Pump Truck		24			
1214		Bulk Truck		24			

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By JOE, JOSH, EVAN, ERNIE

Received By [Signature]

Customer or His Agent