



CEMENTER'S WELL SERVICE, INC.

P.O. BOX 336220 • GREELEY, CO 80633 • (970) 353-7299 • FAX (970) 353-7712

OUR INVOICE

200206

(P.O.# 178849)

Date	11/22/11	Well Owner	Synergy Resources	Well No.	13-260	Lease	Leffler
County	Weld	State	Colorado			Field	
Charge to	Ensign us Drilling					Charge Code	
Address	P.O. Box 17805 (Ensign 33)					For Office Use Only	
City, State	Denver Colorado 80217						
Pump Truck No.	1201	Code		Bulk Truck No.	1217	Code	
Type of Job				Depth	Ft. 500	To	
Surface	8 5/8" CSG #24			Bottom of Surface	Ft. 490	To	
Plug				Plug Landed @	450	Ft.	Time On 2115
Production				Pipe Landed @	490	Ft.	Time Off Plug Down 035

Reference No.	Description	Qty.	Meas.	Unit Price	Amount	
	Pump Truck Charge					
	Cement Neat ✓	350	SKS			
	Poz. Mix					
	Calcium Chloride	3%				
	Gel % Flo-Cele 1/4 #Per Sack					
	Handling Charge					
	Hauling Charge					
	Additional Cement					
8 5/8"	Guide Shoe	1				
"	Baffle Plate	1				
"	Centrallizers	3		70.00		
"	Cement Basket	1				
	Box Thread Lock	1				
	Total Slurry vol 13.5 BBLs cement					
	Mix rate 4 Bpm / Disp rate 5 Bpm					
	Slurry vol 1.18 cu ft ³ /sk - Slurry wt 14.8 - 15 PPG / Plug					
Remarks: Pre Flush w/ 15 BBL H ₂ O		Tax Reference Code		Sub Total		
Displace w/ 28.5 BBL H ₂ O		State CO 2.9 %		Tax		
Circulate 4 BBL cement		Disc.		Total		
Truck No.	Code	State Mileage	Nebraska	Colorado	Wyoming	Other
1201		Pump Truck		24		
1217		Bulk Truck		24		

We do not assume any responsibility for any damage or conditions resulting from our services. All pricing is subject to review and revision.

Delivered By Jim, Adam, Chris, James

Received By Ephraim Isaac
Customer or His Agent