

SECTION 3, TOWNSHIP 2 NORTH, RANGE 65 WEST, 6TH P.M.

NE SEC. 3
2 1/2" ALUM. CAP
LS 9644

N 00°00'32" E 2507.74'

CANNON 13C-3HZ

(TRUE S 06°29'58" W)

N 00°07'01" E 249.3 72' (C)

NOTES:
BH LOCATION PROVIDED BY CLIENT.
LAND SURFACE USE-IMPROVED PASTURE
SEE ATTACHED MAP FOR ADDITIONAL
IMPROVEMENTS WITHIN 400'.

PDOP= 2.5
GPS OPERATOR: OWEN MCKEE

S 00°26'01" W 2479.58

E 1/4 SEC. 3
3 1/4" ALUM. CAP
LS 13155

S 00°01'52" W 2646.91'

SURFACE LOCATION
GROUND ELEVATION= 4840'
NAD83
LATITUDE= 40.173964°
LONGITUDE= 104.655077°

LATITUDE= 40°10'26.271"
LONGITUDE= 104°39'18.276"

BOTTOM HOLE LOCATION
NAD83
LATITUDE= 40.161753°
LONGITUDE= 104.656890°

LATITUDE= 40°09'42.309"
LONGITUDE= 104°39'24.804"

S 1/4 SEC. 3
66' W.C. FOUND
TO THE WEST
PLS 27269

SE SEC. 3
2" ALUM. CAP
PLS 25937

('BASIS OF BEARINGS) SEE NOTE 3

N 89°30'28" E 2642.35' (C)

N 89°30'28" E 2633.43' (C)

3

N 00°07'01" E | 2651.23' (C)

675' FWL

-46-

0,0

S 89°24'54" W 2637 44'

WELL **CANNON 13C-3HZ** TO BE LOCATED 247' FNL AND 1139' FWL

Index

TERRY D. SANDERS, PLS 30120.
COLORADO LICENSED PROFESSIONAL LAND SURVEYOR
FOR AND ON BEHALF OF P.E. AND

NOTICE: ACCORDING TO COLORADO LAW YOU MUST COMMENCE ANY LEGAL ACTION BASED UPON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BASED UPON ANY DEFECT IN THIS SURVEY BE COMMENCED MORE THAN TEN YEARS FROM THIS SAID DATE OF THIS CERTIFICATION SHOWN HEREON.