

FORM
5A

Rev
06/12

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400273126

Date Received:

04/17/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66561

2. Name of Operator: OXY USA INC

3. Address: PO BOX 27757

City: HOUSTON

State: TX

Zip: 77227

4. Contact Name: Joan Proulx

Phone: (970) 263-3641

Fax: (970) 263-3694

5. API Number 05-077-09348-00

7. Well Name: MCDANIEL

6. County: MESA

Well Number: 2-7B

8. Location: QtrQtr: NENE

Section: 2

Township: 9S

Range: 94W

Meridian: 6

9. Field Name: BRUSH CREEK

Field Code: 7562

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO

Status: PRODUCING

Treatment Type:

Treatment Date: 07/10/2008

End Date:

Date of First Production this formation: 06/08/2008

Perforations Top: 6983

Bottom: 8082

No. Holes: 90

Hole size: 34/100

Provide a brief summary of the formation treatment:

Open Hole: ☐

4 stage of slickwater frac with 7,694 bbls of frac fluid and 256,900 lbs of proppant

This formation is commingled with another formation:

☐ Yes ☒ No

Total fluid used in treatment (bbl):

Max pressure during treatment (psi):

Total gas used in treatment (mcf):

Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment:

Number of staged intervals:

Total acid used in treatment (bbl):

Max frac gradient (psi/ft):

Recycled water used in treatment (bbl):

Flowback volume recovered (bbl):

Fresh water used in treatment (bbl):

Disposition method for flowback:

Total proppant used (lbs):

Rule 805 green completion techniques were utilized: ☐

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 03/09/2012

Hours: 24

Bbl oil: 0

Mcf Gas: 272

Bbl H2O: 20

Calculated 24 hour rate:

Bbl oil: 0

Mcf Gas: 272

Bbl H2O: 20

GOR: 0

Test Method: Flowing

Casing PSI: 552

Tubing PSI: 169

Choke Size: 24/64

Gas Disposition: SOLD

Gas Type: DRY

Btu Gas: 1070

API Gravity Oil: 0

Tubing Size: 2 + 3/8

Tubing Setting Depth: 7797

Tbg setting date: 03/06/2012

Packer Depth:

Reason for Non-Production:

Date formation Abandoned:

Squeeze: ☐ Yes ☐ No

If yes, number of sacks cmt

Bridge Plug Depth:

Sacks cement on top:

Comment:

Form 5A to report repair work which to repair a hole in the tubing.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 4/17/2012 Email joan_proulx@oxy.com
:

Attachment Check List

Att Doc Num	Name
400273126	FORM 5A SUBMITTED

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)