



## Robert L. Bayless, Producer LLC

Post Office Box 168  
368 New Mexico Highway 170  
Farmington, New Mexico 87499  
505-326-2659  
Fax 505-326-6911

621 Seventeenth Street, Suite 2300  
Denver, Colorado 80293  
303-296-9900  
Fax 303-296-0753

June 19, 2012

Director  
**Colorado Oil & Gas Conservation Commission**  
1120 Lincoln St. Suite 801  
Denver, CO 80203

RE: **Weaver Ridge 14-15H**  
(SWSE) 39 FSL, 1564 FEL of Sec14-T1S-R104W  
Lease No. COC58705  
Rio Blanco Co, Colorado

Dear Sir(s),

Pursuant to the filing of Robert L. Bayless Producer LLC Application for Permit to Drill the Weaver Ridge 14-15H, Bayless hereby requests and exception to Rule 318(a) for the above captioned well. This rule 318 (a) states that a well to be drilled 2,500 ft or greater in depth should be located not less than 600 ft from any Lease line.

The bottom hole location of the top of the pay zone of the proposed Weaver Ridge 14-15H horizontal well is located 412 ft away from BLM lease line to the south. This well will only encroach upon oil and gas leasehold controlled by Robert L. Bayless Producer LLC. No third Party or oil and gas lease owner will be encroached upon by the granting of this exception location. Bayless is the sole working interest owner within 600 ft of the horizontal well and the adjacent section to the referenced well. BLM is the mineral interest owner (See BLM waiver attached).

In order to maximize recovery of the Mancos B reservoir on our leasehold without the need of any additional wells it is our belief that drilling at this surface location is necessary as an exception to Rule 318(a) to prudently and thoroughly develop the resource. By locating the well at this surface location and horizontally drilling from this location Bayless will be able to utilize the existing roads and pipelines in the area with minimum surface disturbance.

You prompt granting of this request will be sincerely appreciated.

Sincerely,  
Habib Guerrero  
Operations Engineer  
Robert L. Bayless Producer LLC