

From: [Smalley, Carl](#)
To: [Koepsell, Arthur](#)
Cc: [Tritt, Tannis](#); [Stutz, Billy](#); [Akers, Tracy](#); [Shreve, Mark](#)
Subject: RE: Hoffman Busby 1-24 FORM 2A# 400296936, Mull Drilling
Date: Friday, June 22, 2012 10:20:00 AM
Attachments: [Hoffman Busby Location Drawing Display 062212.pdf](#)

Arthur

As we discussed on the telephone: Attached is the location drawing demonstrating that the proposed well pad will indeed have no apparent improvements within the 400 feet radius. When the pad is turned perpendicular to county road 42, the radius to the East becomes a total of 550 feet. The Hoffman Busby is staked 660 feet from the east line. This adjustment of the well pad will annex county road 42 outside the 400 feet radius.

Mull Drilling Company Inc.
Carl Smalley
Environmental Manager
office 719-767-8805
cell 719-342-1812

From: Koepsell, Arthur [Arthur.Koepsell@state.co.us]
Sent: Tuesday, June 19, 2012 4:49 PM
To: Smalley, Carl
Subject: Hoffman Busby 1-24 FORM 2A# 400296936, Mull Drilling

Carl,

The COGCC is reviewing the Form 2A (#400296936) for the Mull Drilling Hoffman Busby 1-24 location, located in the SENE Sec 24 T14S R45W Cheyenne County, Colorado. The COGCC requests the following changes regarding the data submitted on or attached to the Form 2A prior to passing the Oil and Gas Location Assessment (OGLA).

Location Drawing

The included location drawing shows county road 42 within the 400 foot improvement radius. Please provide a location drawing that displays the distance from the location to the road.

If you have any questions or concerns please feel free to contact me.

Thanks,

Arthur

Arthur W. Koepsell, P.G.
Oil & Gas Location Assessment Specialist
Southern Area

Oil and Gas Location Assessment
Colorado Oil and Gas Conservation Commission
1120 Lincoln St. Suite 801
Denver Colorado 80203
Phone (303) 894-2100 ext. 5148