

FORM
5A

Rev
06/12

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400324261

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100185
2. Name of Operator: ENCANA OIL & GAS (USA) INC
3. Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-
4. Contact Name: Marina Ayala
Phone: (720) 876-5905
Fax: (720) 876-6905

5. API Number 05-045-20411-00
6. County: GARFIELD
7. Well Name: HMU Federal
Well Number: 16-10A (J16W)
8. Location: QtrQtr: NWSE Section: 16 Township: 7S Range: 93W Meridian: 6
9. Field Name: MAMM CREEK Field Code: 52500

Completed Interval

FORMATION: WILLIAMS FORK Status: PRODUCING Treatment Type: FRACTURE STIMULATION

Treatment Date: 07/11/2012 End Date: 07/21/2012 Date of First Production this formation: 07/27/2012

Perforations Top: 8133 Bottom: 11488 No. Holes: 360 Hole size: 0.42

Provide a brief summary of the formation treatment: Open Hole: ☐

Stages 1-12 treated with a total of: 209,899 bbls of Slickwater, 243,158 lbs 100 Sand.

This formation is commingled with another formation: ☐ Yes ☒ No

Total fluid used in treatment (bbl): 209899 Max pressure during treatment (psi): 8042

Total gas used in treatment (mcf): 0 Fluid density at initial fracture (lbs/gal): 8.50

Type of gas used in treatment: Max frac gradient (psi/ft): 0.79

Total acid used in treatment (bbl): 0 Number of staged intervals: 12

Recycled water used in treatment (bbl): 209899 Flowback volume recovered (bbl): 32900

Fresh water used in treatment (bbl): 0 Disposition method for flowback: RECYCLE

Total proppant used (lbs): 243158 Rule 805 green completion techniques were utilized: ☒

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 08/05/2012 Hours: 24 Bbl oil: 0 Mcf Gas: 2693 Bbl H2O: 400

Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 2693 Bbl H2O: 400 GOR: 0

Test Method: Flowing Casing PSI: 1210 Tubing PSI: Choke Size: 64/64

Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1170 API Gravity Oil: 0

Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth: 0

Reason for Non-Production:

Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.

Comment:

Tubing has not been landed on this well. Encana will land tubing in 2013, a new 5A will be submitted.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Marina Ayala

Title: Permitting Technician Date: _____ Email marina.ayala@encana.com
:

Attachment Check List

Att Doc Num	Name
400324285	WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)